Errata 1

Manual: 22398

Manual Index: 01

Table of Contents:

1. Reference: Page 1-8, Chapter 1.5.2, Figure ..... 1 - 3
2. Reference: Page 2-16, Chapter 2.8.2, Table ..... 1 - 3
3. Reference: Page 2-19, Chapter 2.10, Table ..... 1 - 4

© PEP Modular Computers GmbH

This page was intentionally left blank.

1. Reference: Page 1-8, Chapter 1.5.2, Figure

The referenced information (legend to figure) is revised as follows.

The functionality of the LED1 Group LED's for IUC860 boards, index 00, is incorrect. The functionality is as follows:

LED1 Group
Green ("ACT."): Data rate: on = 100 Mbps; off = 10 Mbps
Green ("LNK."): Data send/receive
Green ("SPEED"): Link established in both directions

2. Reference: Page 2-16, Chapter 2.8.2, Table

The referenced information (description in table) is revised as follows.

The functionality of the LED1 Group LED's for IUC860 boards, index 00, is incorrect. The functionality is as follows:

Table 2-9: System Status Indicators

G	FP DES.	COLOR	NAME	DESCRIPTION
LED1	ACT	GREEN	LED1AC	This LED indicates the data rate of the Ethernet link. When on the speed is 100 Mbps; off it is 10 Mbps.
	LNK	GREEN	LED1LN	This LED indicates that data are being transmitted or received via the Ethernet link. It blinks when there is traffic on the link.
	SPEED	GREEN	LED1SP	This LED indicates the integrity of the Ethernet link. When on the link is established in both directions.
LED2	U	GREEN	LED2G	This LED blinks during startup indicating that the system is being initialized (bootstrap loading in progress). After system initialization has been completed it is on steady and is available for use by the application program. Refer to chapter 4 (BOARD_CON_STA_REG_1 register) for setting of this LED.
	W	YELLOW	LED2Y	This LED is used to indicate the status of Watchdog Timer enabling. When on, the Watchdog Timer is enabled.
	H	RED	LED2R	This LED is available for general use and is application dependent. It is off if not used. Refer to chapter 4 (BOARD_CON_STA_REG_1register) for setting of this LED.

© PEP Modular Computers GmbH

3. Reference: Page 2-19, Chapter 2.10, Table

The referenced information (table contents) is revised as follows.

For IUC860 boards, index 00, RESETIN on pin 2 does not function.

© PEP Modular Computers GmbH