Errata 1

Manual: 25780

Manual Index: 01

Table of Contents:

1. Reference: Page 1 - 9, Chapter 1.6, Table 1-3..... 1 - 3

This page has been intentionally left blank.

1. Reference: Page 1 - 9, Chapter 1.6, Table 1-3

The referenced information (table) is revised as follows.

The table row:

CPCI Bus	One, 132-pin, female, six row connector (standard CPCI type connector for J1)

is changed to read:

CPCI Bus	One, 132-pin, female, six row connector (standard CPCI type connector for J1) PCI Interface: Universal; 3.3V (5V-tolerant); the VI/O pins are not connected

This page has been intentionally left blank.