Errata 1

Manual: 20826

Manual Index: 02

Table of Contents:

1. Reference: Page 2 - 37, Chapter 2.9.4, Table 2-25 ..... 1 - 3

© 2003 Kontron Modular Computers GmbH

This page has been intentionally left blank.

© 2003 Kontron Modular Computers GmbH

1. Reference: Page 2 - 37, Chapter 2.9.4, Table 2-25

The referenced information (description in table) is revised as follows:

The following text is added:



Warning!

IRQ5 should normally have only **one** source enabled, otherwise improper system operation may result.

If more than one source is required to be enabled, contact Kontron's technical support before implementing the IRQs.

For events that are not time critical, such as ENUM, DERATE, etc., polling should be considered instead of using an IRQ.

© 2003 Kontron Modular Computers GmbH

This page has been intentionally left blank.

© 2003 Kontron Modular Computers GmbH